SIM IN A BOX™

ASSEMBLY INSTRUCTIONS

4:3 EAGLE

FORESIGHT SPORTS


8’11”
16’
11’
4:3 Eagle
SIM IN A BOX
PLAYER 1
FORESIGHT SPORTS
PEBBLE BEACH


Blackout Panel
(Excluding Birdie)
Outer Side Walls
Securing Strips
Inner Side Walls
Lid Panel
Above Screen Panel
Front Screen
Rear Mesh Screen
Hitting Mat Turf
Hitting Mat Rubber Tray-4 Corners Edges
Hitting Mat Rubber Tray-4 Side Edges
PC
Projector
Wireless Keyboard
(Excluding Birdie)
PC Cart
These 3 Frame Sections will be Shorter for the Birdie and 4:3 Eagle
Allen Wrench and Screws
Shock Cord
Fish Tape
Ratchet Rope and Hooks
Power Strip
Zip Ties
Frame Sections
Turf Rolls

Falcon
Ace

QuadMAX
Eagle
4:3 Eagle

GC3
Birdie
SIAB Play

GCHawk
Albatross



Connect Frame Sections according
to the Color Coding

Secure Frame Connections together
with provided Allen Wrench and Screws




1
Tilt the Left Wall Frame Vertical and Slide the Connecting Post into its Matching Color End


2
Secure with Provided Allen Wrench and Screw




1
Tilt the Right Wall Frame Vertical and Slide the Connecting Post into its Matching Color End
2
Secure with Provided Allen Wrench and Screw








Drop Rear Cross Bar into the Rear
Trays of the Left and Right Side Walls
Secure with Provided
Allen Wrench and Screws






Drop Rear Cross Bar into the Rear
Trays of the Left and Right Side Walls
Secure with Provided
Allen Wrench and Screws



Rear Mesh Screen

Ratchet Rope


Feed the Rope through the Ratchet Hook
Thread the rope through the Grommets on the Top Edge of the Rear Mesh Screen starting with the 2nd Grommet Hole
End with the Grommet Hole 2nd from the Last






End of
Rope and
Hook


Tie Rope
Securely to
the Hook


Hook the ends of the rope
to the Triangle Weld Hooks
in the Upper Frame Walls






…raising the Mesh Screen Up.
3
…and Pull…
2
Grab the Excess Rope from the Ratchet Hook…
1
Rear Mesh Screen Raised


Rear Mesh Screen
Raised - Secure
further with Zip Ties


Thread a Long Zip Tie through the End Grommet and the Triangle Weld Hook
Thread a Long Zip Tie through the End Grommet and the Triangle Weld Hook


Thread 2 More Long Zip Ties through Grommets/
Around the Rope and Over the Rear Cross Bar
to keep Rear Mesh Screen from drooping


Pull Zip Ties as hard as you can on each end to keep Screen Nice and Tight
Pull Zip Ties as hard as you can on each end to keep Screen Nice and Tight


1
Attach Velcro Loop on this Edge…
…with the Velcro Hook on the back of the Frame Edge


2



Proceed with the same process on the Right Side


Tight and Secured Rear Mesh Screen

Securing Strips


Securing Strips
will be
approximately
the same Height
as the Vertical
Posts


1
Attache the Velcro Hook on the inside of the Securing Strips to the Velcro Loop on the back of the Rear Mesh Screen Flap Edge


2
Approximately 2” should be Overhanging past the Vertical Post Edge


1
Attache the Velcro Hook on the inside of the Securing Strips to the Velcro Loop on the back of the Rear Mesh Screen Flap Edge


2
Approximately 2” should be Overhanging past the Vertical Post Edge


Top
Left
2” Overhang will fold over to adjacent Vertical Post Edge


Top
Right
2” Overhang will fold over to adjacent Vertical Post Edge


2” Overhang will fold over to adjacent Vertical Post Edge
Bottom
Left


2” Overhang will fold over to adjacent Vertical Post Edge
Bottom
Right


Securing Strips should look like this when finished
Securing Strips should look like this when finished

Front Screen

1



Attach the Velcro Loop on the Back of the Front Screen to the Velcro Hook on the front of the Rear Mesh Screen

2


Front Screen Secured to Rear Mesh Screen

Shock Cord

Fish Tape


Feed the Fish Tape through the Cable Pocket on the Bottom of the Rear Mesh Screen
Tie one end of the Shock Cord to the Triangle Weld of the Bottom Frame Wall


Feed the Fish
Tape all the
way through to
the other side


Tie the Other End
of the Shock Cord
to the End of the
Fish Tape


Pull the Fish Tape and
Tied Shock Cord End
back through the Cable
Pocket on the Bottom of
the Rear Mesh Screen


Untie the Shock Cord
from the Fish Tape
Pull the Shock Cord as much
as you can until there is
no more stretching…
…and tie to the Triangle
Weld Hook on the Bottom
Frame Wall


Tied Left
End


Tied Right
End


Cut the Excess Shock Cord or
Tuck it Behind the Screen


Carpet Lid Panel


Make sure the Front Edge is the Velcro Hook Edge - The Velcro Hook should be Facing Down
Attach Carpet Lid to the Hook Velcro on Top of the Frame
Carpet Lid Panel Attached



Wrap the Front Excess Edge with the Velcro Hook around the Front Cross Bar and attach to bottom part of the Carpet Lid Panel



Inner Side Walls


2
Press the Carpet Material to the Velcro Hook Strip as much as possible for a secure seal
1
Attach the Inner Side Wall Edge to the Vertical Velcro Hook Strip on the Front of the Front Screen



Once the Inner Side wall is secured to the Front Screen, Pull the Front Edge Forward and Wrap it around the Front Vertical Post, securing it to the Velcro Hook on the Back Edge Corner of the Post


2


1
Repeat for the
Opposite Side


Repeat the process for the Opposite Side


Above Screen Panel



1. The Edge with no Velcro will Secure to the Horizontal White Velcro Hook Strip on the Top Edge of the Front Screen

2. Blue Lines represent the Velcro Hook on the INSIDE of the Panel that will Secure to the Black Carpet Panels

When Attaching the Top Edge, make sure to Pull That Edge Forward creating a Slant when Securing to the Carpet Lid Panel






Outer Side Walls


All Edges of the Outer Side Walls Should be the Exact Dimensions of the Frame Side Walls and should Line Up on All Edges




1


3


2


4

Blackout Panel

(Excluding Birdie - Birdie Orders can Skip this Installation Step)


1


2


4
Top Velcro Hook Edge of the Blackout Panel will Secure to the Back Edge of the Carpet Lid Panel


3


Turf Rolls


1


2
1st Turf Roll


3
2nd Turf Roll


1
Make sure the 1st Turf Roll lines up against the 12 inch Tail Frame Base Behind the Screen


2
Line the Back of the 2nd Turf with the Front of the 1st Turf


3

Hitting
Mat Turf

Hitting Mat
Rubber Tray-4
Corners Edges

Hitting Mat
Rubber Tray-4
Side Edges


1
Corner


2
Side


3
Side


4
Corner


5
Corner


6
Side


7
Side


8
Corner


9
Place the Hitting Mat Turf into the Hitting Mat Rubber Tray


10


PC Cart
Projector
PC

Place the Projector and the PC on the Shelves as Shown


Eagle
Ace
4:3 Eagle
The Back of the PC Cart should be 192
inches from the back of the Frame Tail Base


Connect Power and HDMI
Cables as shown
Power
Strip
PC
Power
HDMI
Projector
Power

Turn On the Projector and PC


Focus
Tab
Zoom
Tab
Adjust the
Zoom Tab to
Enlarge the
Display
Image as
much as
Possible


INPUT
VGA
VIDEO
HDMI
AUTO
MENU
OK
KEYSTONE
IMAGE
FREEZE
PATTERN
SCREEN
LAMP
MUTE
INFO.
BLANK
D.ZOOM
VOLUME
TIMER
3rd
Hole
Par 4
Index 9
1 2 3 4
The Display Image will most likely need to be adjusted


H/V Keystone
Corner correction
Curved correction
Reset value
Select Down to
Corner Correction
and Press OK
INPUT
VGA
VIDEO
HDMI
AUTO
MENU
OK
KEYSTONE
FREEZE
PATTERN
LAMP
MUTE
INFO.
BLANK
D.ZOOM
VOLUME
TIMER
Press the Keystone Button

A Corner Correction
Cursor will Appear



Use the Arrows on the Remote to Line
the Display Image with the Screen

Once Finished with the Corner, Press OK and it will move to the Next Corner to Adjust

Use the Arrows on the Remote followed by Pressing the OK Button to continue the Process for all 4 Corners until the Display Image Perfectly Fits the Screen

Continue the Corner Correction Process

Display Image Calibrated to Fit the Screen


FORESIGHT
3rd Hole
Par 4 Index 9
1 2 3 4
Ready
Ball Only Mode
USB-C Cable
QuadMAX
Power Cables

Place the Launch Monitor on the Hitting Mat close to the Front Edge



Connect the Power and USB-C Cables from the QuadMAX to the PC and Power Strip

The QuadMAX can also hold a Charge and Connect to the PC Wirelessly to eliminate Cable Visibility


FORESIGHT
Ready
Ball Only Mode
Installation
Complete